

FIERO FOCUS - Index of Articles

NORTHERN ILLINOIS FIERO ENTHUSIASTS

From: July 1994 To: February 2010 (See end of list for ordering instructions)

Section 0: Care, Maintenance, & Lubrication

Long Term Maintenance Program; 3-4/99, p.6
Winter Storage; 9/98, p.6; 3/99, p.11; 7-8/99, p.7
Starting after Long Storage (Class R/T); 5-6/05, p.5
Maintenance Tips; 5-6/03, p.7
Terminology & Abbreviations; 5-6/09, p.6; 7-8/09, p.5
Fiero Tips; 9/96, p.13
Washing Tips; 9-10/00, p.6; 7-8/07, p.14
Acid Rain Marks; 11-12/03, p.7
Paint Swirl Marks; 9-19/01, p.9
Paint Cleaning with Detailing Clay; 9/96, p.9; 1-2/09, p.7
Waxes & Sealants; 7-8/99, p.9; 3-4/01, p.10; 5-6/01, p.11; 7-8/01, p.10;
3-4/02, p.6; 5-6/02, p.6; 3-4/03, p.14; 3-4/04, p.11; 5-6/06, p.6
Wax Stain Removal from Trim; 5-6/04, p.12
Detailing Tips; 1/97, p.3; 9/98, p.11; 11-12/02, p.7; 5-6/06, p.4; 7-8/06,
p.4; 9-10/06, p.4
Cleaning Tinted Windows; 7-8/05, p.13
Carpet & Upholstery Cleaner; 3-4/08, p.6
Interior Odors; 5-6/01, p.10
Tire Dressing; 11-12/04, p.5
Windshield Wiper Cleaning; 1-3/07, p.11

Section 1: Heating and Air Conditioning

Heater Core Replacement; 9/94, p.2; 1-2/00, p.10; 5-6/07, p.12
Rebuilding the Heater Module; 3-4/07, p.7
AC Basics; 5-6/01, p.12 (Meeting 3/17)
R-12 Substitute (Auto Frost); 11/97, p.15
Foul Fiero Odor (fungus on AC evaporator); 11-12/01, p.10

Section 2: Frame and Bumpers

Clunking Noise from Chassis; 3/97, p.10

Section 3: Steering, Suspension, Wheels & Tires

Steering

Fiero Steering Wheels; 1-2/00, p.5
Repairing Loose Tilt Steering Column; 1-2/03, p.6
1988 Steering Rack Solutions; 5-6/99, p.10
Fiero Power Steering; 3/97, p.8
Four Wheel Alignment; 7/94, p.3; 9-10/01, p.10

Suspension

Suspension Restoration & Modification; 5-6/09, p.8
Why '88 Suspension is Better; 7-8/06, p.6
Shock Information; 9/98, p.10

Wheels & Tires

Wheel/Tire Mounting-Gray Stem Caps (for best balance & fit); 1-2/10, p.18
Wheel Basics; 5-6/03, p.9
Wheel Restoration (Club Meeting - November 14); 1-2/99, p.13; 3-4/01, p.6
9-10/02, p.3; 5-6/03, p.2
Wheel Cleaning & Polishing; 1/98, p.6; 11-12/98, p.10; 3-4/02, p.9
Wheels for Your Fiero; 7/97, p.14
After Market Wheels; 5/95, 6 page insert
Locking Lug Nuts; 5/97, p.8
Tire Checking; 1-2/01, p.10
Tire Specifications & Guide; 11/96, p.8
Performance Tires for 13" Wheels; 5/98, p.8

Section 4: Final Drive

Bucking in Gear; 7-8/03, p.6

Section 5: Brakes

Brake Fluid Tips; 5/97, p.9
Brake Failure due to Brake Line Strangulation; 9/97, p.10
Brake Bleeding Check Valve; 7-8/00, p.6
Brake Caliper Replacement; 9-10/02, p.9
Large Rotor Brake Kit (March Mega-Meeting); 5-6/04, p.9
Fiero Brakes (club mtg 2/17/07); 5-6/07, p.11

Section 6: Engine

General

Decarbonization; 11/95, p.9
Difference Between 300hp Naturally Aspirated & Turbo Engines; 9-10/07, p.5
Drivebelt Tensioner; 7-8/02, p.10
Simple Duke Mods; 11-12/06, p.7
V6 Power Gains (March Mega-Meeting); 5-6/04, p.11
Edelbrock Chrome Valve Covers; 11-12/02, p.7

Air / Fuel

Free Horsepower (Air Cleaner Modifications); 4/00, p.10
IAC (Idle Air Control Valve) - idle problems; 1-2/05, p.5
diagnosing problems; 3-4/08, p. 5
Gasoline (use regular); 11-12/01, p.10
Fuel & Fiero Storage; 7/95, p.9
Fuel Pumps & Filters; 3-4/01, p.11; 9-10/01, p.11
Fuel System Diagnosis (pump, sender, gauge); 9-10/09, p.6
Hot Fuel Pump; 5-6/99, p.7
Hi-Output Fuel Pump; 1-2/99, p.12
Adjustable Fuel Regulator for V6; 11-12/02, p.7
Adjustable Fuel Regulator on Holly TBI for '84-86 4 cyl; 7-8/02, p.9
Demystifying Fuel Injectors: 3-4/04, p.6
Fuel Injector Cleaning; 11-12/02, p.7
Bored Out Throttlebody - Extra HP; 1-2/01, p.7
Throttle Stop Screw (Minimum Air Setting; 3-4/08, p.5
V6 Throttle Body Heater - not needed in warm climates; 5-6/02, p.8
Gas Pedal Binding / Throttle Plate Sticking; 1/95, p.7

Cooling / Antifreeze

Watch That Water Level; 11-12/06, p.13
Water Pump Replacement for V6; 11-12/02, p.11
Fan Switch; 1/96, p.12; 3/97, p.10; 5-6/03, p.8; 9-10/09, p.7
Belts & Hoses (Overlooked Maintenance); 1-2/01, p.10
Changing Anti-Freeze; 1/97, p.8
Coolant Tube Drain Plug Removal; 5-6/99, p.11
Coolant Tube Repair; 7-8/04, p.5
Coolant Hose Inspection; 5-6/02, p.11
Radiator Painting (Restoration Tip); 1-2/01, p.10

Electronics

ECM Modes of Operation; 1-2/09, p.7; 3-4/09, 7
ECM Tuning; 11-12/09, p.5; 1-2/10, p.9
Engine Scanner; 1-2/02, p.8; 5-6/05, p.12; 9-10/09, p.5
PROM Chip Function; 7-8/08, p.11

PROM Chip Upgrade for V6; 1-2/04, p.10
V6 Sensor Location and Function; 1-2/08, p.12
Coolant Temperature Sensor; 1/96, p.12; 3-4/07, p.6; 7-8/08, p.5
MAP Sensor; 1-2/05, p.7
MAP, IAT, & MAF Sensors; 5-6/08, p.6
Oxygen Sensor; 3/96, p.11; 11-12/08, p.5
Throttle Position Sensor; 3/97, p.9; 7/97, p.10; 1-2/08, p.5
Engine Wiring; 1-2/07, p.5; 3-4/07, p.5

Exhaust

Exhaust System Upgrades; 3-4/02, p.12
Exhaust Manifold Removal, Repair & Porting; 9/96, p.10; 5-6/05, p.11
Exhaust Manifold Bolts - stainless steel with locktabs; 7-8/02, p.10
V6 Exhaust Manifold/Breather Reroute (Air Cleaner Inlet Plug); 3/98, p.10
Exhaust Pipes & Hangers; 7/97, p.10
Exhaust Backpressure/Bad Catalytic Converter; 5-6/99, p.8; 5-6/02, p.9
Emissions Test Failure - Bad Catalytic Converter; 3-4/03, p.7

Ignition

Spark Plugs; 7/95, p.9
Platinum Plugs and Ignition Systems; 9-10/99, p.8
Specialty Spark Plugs; 5/96, p.10
Spark Plug Wires; 5-6/02, p.10
Ignition Control Module & Distributorless Ignition System; 9-10/08, p.5
Pickup Coil Replacement; 5/96, p.8
Pickup Coil / Tachometer Flicker; 9/95, p.6
Distributor Rebuild & Parts Numbers; 5-6/05, p.11
Distributor Rotor & Tachometer Filter / Tachometer Flicker; 11/95, p.9
Timing Advance Kit (Product Review) - bad news; 1-2/03, p.4

4 Cylinder

Iron Duke Rocker Replacement; 3-4/03, p.6

6 Cylinder

Ideas for V6 Power Gains; 9-10/96, p.5

Section 7: Transmission

Torque Converter Lock-up Solenoid with an anti-lock switch mod; 1-2/06, p.6
Transmission "chuggling"; 5-6/99, p.7
Getrag 5-Speed Transmission (Design/Wear/Overhaul/Conversions); 11/97, p.12
Clutch Problems; 11-12/02, p.10
V-6 Clutch Replacement; 11/97, p.14; 11-12/98, p.6; 3-4/99, p.10;
3-4/02, p.7

Aluminum Clutch Pedal Problems; 5/98, p.11
Clutch Pedal Creaks; 5/95, p.7
Clutch Pedal Installation; 9-10/02, p.6
Clutch Slave & Master Cylinder Bleeding Procedures; 5/98, p.12; 7-8/02, p.8
Clutch Actuator Rebuild & Bleeder Tool; 9-10/02, p.7
Clutch Line Deterioration; 5-6/07, p.5
Downshifting - Bad Habit; 11-12/01, p.10

Section 8: Chassis Electrical

Electrical Diagram Symbols; 3-4/99, p.13
Battery Problems / Crazy Electronics; 1-2/99, p.10
Electrical Ground Repairs; 7/98, p.9
Alternator Reinforcement Plate; 7-8/05, p.5
Fuel Gauge Problems; 9/95, p.5
Pegging Temperature Gauge Fix; 4/00, p.8
Cruise Control Troubleshooting; 7/98, p.6
Headlight Problem Diagnostics; 9/95, p.6
Headlight Alignment Adjustment; 5-6/99, p.15
Headlight Motor Replacement Gears; 1/98, p.10; 5-6/02, p.10; 7-8/02, p.10
1-2/04, p.4
Switch for Headlight Door Motors; 1/97, p.8
Brighter Headlights (Brightlite - Xenon filled); 11/97, p.15; 7-8/02, p.10
Parking Light Switch Repair; 9/97, p.8
Adding a Third Turning/Brake Light; 1-2/04, p.6
Dash Lights Out; 3/95, p.7
Warning Chime Modification; 1/97, p.8
Trunk Light Assembly Repair; 11-12/03, p.6

Section 9: Parts / Accessories and Vendors

Parts and Accessories

GM Parts (Wholesale ant 25% Discount); 3/98, p.9
How to Repair Your Tape Deck; 3-4/03, p.5
Stereo System Upgrades and Modifications; 1-2/02, p.9
Late Model Delco Stereo/Cassette/CD Player upgrades; 4/00, p.6; 7-8/01, p.10
Radio and Speaker Installation Tips; 4/00, p.7
Subwoofer Replacement or Repair; 5-6/00, p.10; 5-6/01, p.11
Speaker Noise; 7/98, p.9
Do-It-Yourself Fiero Cupholder; 1/97, p.9
Switch Tray; 1-2/05, p.6

Vendors

CCI - interior color & fabric / vinyl repairs; 5/98, p.10
Powder Coating & Ceramic Coating; 9-10/09, p.3+C247
Steering Wheel & Shifter Leather Recovering; 9-10/09, p.3

Section 10: Body

Fiero Body Panels; 3/98, p.8; 5-6/01, p.12 (Meeting 2/17)
Body Panel Repair; 5-6/06, p.12
Repairing Upper (SMC) Panels; 1-2/02, p.14 (Meeting 11/17)
Front Bumper Cover Repair; 3/98, p.7
Rust Repair; 5/95, p.7; 9/95, p.6; 9/96, p.12; 7/98, p.9
Rust on Cooling Tube Brackets; 3/98, p.10
Battery Tray Rust, Repair, Replacement; 3/97, p.10
Subject: Paint; 1-2/01, p.11
Airbrush Touch-up (Club Meeting February - 20); 1-2/99, p.15
Powder & Ceramic Coating; 5-6/03, p.11
Trunk Lid Torque Rod Replacement; 7/97, p.11
Wing Stand Replacements; 5-6/02, p.10
Windshield Defects / Damage; 7-8/00, p.8
Windshield Polish; 1/98, p.10
Windshield Wiper Arm Removal; 5-6/99, p.11
Windows can Roll All the Way Down; 5-6/02, p.8
Window Tint Removal; 5-6/01, p.10
Window Dew Wipe Strip Replacement; 3-4/07, p.12
Sunroof, Door, & Trunk Gasket Replacement; 5-6/07, p.12
Sunroof Rattle; 5-6/99, p.11
T-Top "P" Seals; 1-2/02, p.8
T-Top Tinting/Scratch Remedy; 11-12/07, p.7
Replacing Rear Quarter Glass on GT; 1-2/99, p.11; 1-2/01, p.8; 3-4/01, p.5
Key Replacement using Key Knock-Out Plugs; 9/96, p.9
One Car - One Key; 1-2/99, p.8
Door Hinge Replacement; 3-4/07, p.12
Door Lock Replacement; 9/97, p.9
Matching Locks to Your Key; 3/98, p.10
Remote Keyless Entry; 5-6/02, p.10
Indy Pace Car Decals; 3-4/02, p.15

Section 11: Interior

Interior Disassembly; 9/98, p.9; 11-12/98, p.8; 1-2/99, p.7; 3-4/99, p.8

Interior Trim - Glue Repair; 3-4/99, p.6; 11-12/02, p.7
Leather Interior for Your Fiero; 1-2/99, p.5
Seat Track Refinishing; 11-12/04, p.10
Recovering Fiero Dash Speaker Grills; 7-8/99, p.5
Manual Mirror Control Housing Repair; 3/97, p.9; 11-12/05, p.14; 3-4/07,p.12
Console Make-Over; 7/98, p.8
Club Meeting - January 22nd (Interior tips on consoles, roof liners,
seats, etc.); 4/00, p.11
Sun Visor Restoration; 5-6/05, p.13
Door Emblem Detailing; 1-2/01, p.9
Door Carpeting Replacement; 3-4/07, p.13

Section 12: Fiero Conversions

Body

Mera; 1/96, p.7
Aldino Fiero; 9-10/06. p.7
Popular Rebody Kits; 7/97, p.13
Fiero Convertibles; 3-4/06, p.8
Lower Quarter Intake Scoops; 1-2/02, p.8
Custom GT Taillight Assemblies; 7-8/03, p.2
Iridescent-like Speciality Paint Glows & Changes Colors; 3/98, p.11

Engine

Engine Swaps (Series:3.4DC, 3.8SC); 11-12/05, p.4
3.4L Fiero; 9-10/01, p.8; 1-2/06, p.4
3.800SC Conversion; 9-10/03, p.5
Northstar DOHC; 1-2/06, p.4; 3-4/06, p.4
V-8 Conversions by V-8 Archie; 5/98, p.10; 1-2/99, p.15; 5-6/03, p.4
V-8 Conversion; 9/98, p.8; 3-4/06, p.4
Sprint Headers on V-6; 7/97, p.15

Transmission

Other

Front & Rear Conversion (Grand Am/Baretta rotors & calipers); 11-12/01, p.6
Front Brake Conversion (Baretta); 1-2/02, p.8
Rear Brake Conversion (Grand Am vented rotors & calipers); 3/97, p.9
Sound System Upgrades; 11/95, p.10-12
Overhead Console Modification; 5-6/00, p.6
Seat Belt Activated Power Door Locks; 5-6/00, p.9
Underhood (front & rear) Mirrors; 3-4/07, p.13

Section 13: History / Information / Miscellaneous

Fiero Facts; 5-6/00, p.5
Fiero Design Concepts; 11/95, p.7
Fiero Technical Features & Engineering Innovations; 1/96, p.8
Pre-Pilot Fiero; 1-2/08, p. 4; 3-4/08, p.4
Fiero Manufacturing Concept: Innovative Assembly; 3/96, p.8
The All New Fiero Plant; 1-2/10, p6
Fisher Body Pontiac Assembly Plant - Birthplace of the Fiero; 1-2/10, p.10
Fiero Factory Workers - Family Picnics; 11-12/08, p.4
In the Beginning....; 9-10/04, p.5; 11-12/04, p.4
Fiero Day - September 13, 1983 (Congressional Record); 5-6/09, p.4
Unique History of Fiero - Bartemeyer's Bits: 5-6/08, p.4; 3-4/09, p.8
1984 Fiero Dealer Promotion; 11-12/07, p.6
"84 Fiero Desk Pen Set (for Pontiac HQ management); 5-6/09, p.5

Fiero Article: "When Everybody Wanted a Fiero" Excellent 4 page article
on magazine coverage of the new Fiero; 1-2/03, p.8
Fiero 1988 "Long Lead Press Kit" Reprint; 1/98, p.8
1990 GTP and Coupe pictures; 9-10/08, p.4
P-2 Second Generation 1993 Fiero Concept; 7-8,2008, p.4
The Last Fiero Made; 7-8/03, p.8
Fiero Milestones (100,000+ miles); 1-2/99, p.10
Fiero - 10 Years Ago ...; 3/98, p.6; 9/98, p.5; 11-12/98, p.5
Fiero - 20th Anniversary; 5-6/04, p.4; 7-8/04, p.4
1986 Fiero At 20; 11-12/06, p.6
1987 Fiero AT 20; 11-12/07, p.5
1988 Fiero AT 20; 11-12/08, p.7
Fiero As A Survivor; 1-2/09, p.12
Fiero V8 by Pontiac Engineering; 11-12/09, p.6
Fiero 4-Wheel Steering Prototype; 7-8/09, p.4
Fiero Indy PPG Pace Car; 1-2/09, p.4; 3-4/09, p.4
Fiero PPG Pace Car That Did Not Get Built; 9-10/09, p.4
Fiero Delta 204T (SOHC 2.0 Turbo); 5-6/07, p.8
Restoration vs. Preservation; 3-4/03, p.4
Fiero RPO Codes; 7/96, p.14
Fiero MPG Ratings per year & engine/transmission; 3-4/08, p.10
Fiero Values - Collectible or Not; 5/96, p.11; 5/97, p.12; 5/98, enclosure
in March/April issue in '99,'00,'01,'02,'03,'04,'05,'06,'07,'08
Fiero Potential Future Worth; 5-6/09, p.10
Fiero Appraisals; 5-6/05, p.12

Fiero Safety; 1/95, p.3; 5-6/99, p.9
Fiero Auto Insurance; 5/95, p.3;"Collectible Car" 9-10/00, p.5; 7-8/01, p.8
in 1-2/07, p.7; 3-4/07, p.5
Fiero Parts Sources; 11/96, p.10; 1-3/07, p.3
NIFE Service Referrals; 7-8/04, enclosure
NIFE History 1991 - 1992; 1-2/01, p.5
NIFE History 1993 - 1994; 3-4/01, p.7
NIFE History 1995 - 1996; 5-6/01, p.7
NIFE History 1997 - 1998; 7-8/01, p.6
NIFE History 1999 - 2000; 9-10/01, p.6
100th Issue Celebration; 7-8/07, p.8
Autocrossing the Fiero; 7/95, p.5; 1-2/02, p.6; 7-8/03, p.4
Roadracing; 3/96, p.7; 3-4/01, p.5; 3-4/06, p.6; 1-3/07, p.8
Cliff Pennock - Man Behind Fiero.nl; 1-2/09, p.8
Fieros on the Internet; 4/00, p.2; 5-6/01, p.3; all issues thereafter
Fieros on TV; 7-8/03, p.6
Fiero Museum; 5-6/07, p.6
Fiero Toy Box; 1-2/99, p.8; 5-6/99, p.6; 7-8/99, p.6; 9-10/99, p.9;
11-12/99, p.9
Fiero Collectible - 1/60 scale die cast 85 GT; 3-4/08, p.7

indxnife.wk4

1/31/10

For a copy of any of these articles, send a written list and \$1.00 for each article payable to NIFE to:

NIFE

Paul Vargyas

2600 Longview Drive

Lisle, IL 60532